https://www.mikrozone.sk/news.php?item.1283

Info, Download

Changes related to a reported bug:

- Fix broken links and add correct links to about dialog.
- Eeschema: highlight the first choice in rescue dialog.
- Eeschema: fix zone properties dialog level setting tooltip.
- Pcbnew: fix segfault when appending a board in GAL mode.
- Remove some useless or incorrect asserts in plot functions.
- Pcbnew: continue loading footprints after first failure.
- Eeschema: don't apply last line width to text thickness in symbol library editor.
- Pcbnew: add option to plot DXF lines in outline mode.
- Pcbnew: add option to plot DXF editable text.
- Pcbnew: fix crash when dragging a track.
- Fix crash when dragging a track.
- Remove leading/trailing white space error message from field validator.

Changes without a bug report:

- Pcbnew: fix bug loading board files written when layers could have numeric names.
- Pcbnew: prevent segfault when outline has no vertices reading P-CAD file.
- Pcbnew: fix tooltip error in copper zones dialog.
- Eeschema: move BOM scripts so they are installed correctly.
- Apply changes from master to GOST page layouts.
- Save text thickness in worksheet editor.
- Fix default line widths for non-mm units in DXF import.
- Better error messages when throwing an I/O error or parse error.
- Cvpcb: fix incorrect assignments when using .equ files and automatic association.
- Fix possible crash and issues when a incorrect fp lib table is loaded.
- Fix crash when writing zip archive file to folder that is not writeable.
- $\mbox{\rm Fix}$ issues in plot functions when used from python scripts.

30.08.2017 1/1